

Service Information

Diagnostic Device Hardware & Windows®

Subject: Windows 10® ODIS Service Devices – Feature Updates Date: Apr. 25, 2018

1.0 – Introduction


1.1 – General Information

Windows has discontinued support for **feature update version 1607** and will no longer allow Windows 10 devices running this version to download security updates.

What this means for you; if you remain at **Feature update version 1607 or older**, you will no longer receive Windows security updates, which may leave your device vulnerable to cyber-attacks and other malicious software. The downside to updating from this older feature version is that your **ODIS Service Hardware ID will change** and you will be required to request a new **ODIS Service License & Certificate**.

2.0 – How to check which Feature update is currently installed

1. On the Windows Desktop, **right-click** on the Windows button.
2. Click on **Settings**
3. Click on **System**



4. Click on About to display the version.

Edition	Windows 10 Pro
Version	1607
OS Build	14393.2189
Product ID	00330-50516-24941-AAOEM
Serial number	7DTCA27900

Service Information

3.0 – Steps required after checking your feature version

1. If your diagnostic device is running feature update **Version 1607 or lower** and you make the decision to update to the most recent version, your **ODIS Service Hardware ID** will change. You will need to request a new **ODIS Service License & Certificate** from erWin >Vehicle Diagnostics > **Step 2 and 3**.

Note: To update your Windows feature version, simply run Windows Updates on your device.

2. If your feature update Version is higher than **1607**, there is no action required.